



1 CABINET SECTION
SCALE: 1" = 1'-0"



3 RADOME UPPER SUPPORT
SCALE: 1" = 1'-0"

- PROCEDURE**
- INSTALL SHEET METAL EDGING ALL AROUND PERIMETER OF DOOR
 - INSTALL SHEET METAL EDGING ALL AROUND EXTERIOR EDGES AND CORNERS OF ASSEMBLED CABINET
 - INSTALL GASKET ON FRONT FACE OF BOX SECTION,
 - INSTALL MAGNETIC GASKET TO TOP, BOTTOM AND OUTSIDE EDGE OF DOORS
 - LAY FINISHED DOORS IN POSITION ON CABINET (LAYING DOWN/FACE UP) WHILE INSTALLING HINGES TO ASSURE ADEQUATE SPACING FOR MAGNETIC GASKET
 - INSTALL BRISTLE EDGE TO INSIDE EDGE OF DOORS



2 CABINET SECTION
SCALE: 1" = 1'-0"

UNLESS OTHERWISE SPECIFIED
DIMENSIONS ARE IN INCHES

TOLERANCES ON	
2 PLACE	3 PLACE
+/- .01	+/- .005
FRACTIONS	ANGLES
+/- 1/64"	+/- 1°

CONTRACT NUMBER
CONTRACTOR

DRAWN BY
KS

DATE (DA-MON-YR)
01-JUN-04

CHECKER
B TALLENT

ENGINEER

DRAWING APPROVAL

DESIGN APPROVAL

RED RIVER ARMY DEPOT
PRODUCTION ENGINEERING DIVISION, DIRECTORATE OF OPERATIONS
TEXARKANA, TEXAS 75507-5000

RADOME STORAGE CABINET

SECTION VIEWS

SIZE B	CODE IDENT NO. 67101	DWG NO. 2010852	REV
	SCALE AS SHOWN	SHEET 03	OF 06